

ICD-9-CM Coordination and Maintenance Committee
Centers for Medicare & Medicaid Services

Bi-ventricular Replacement

September 27, 2007

Bartley P. Griffith, M.D.

**Chief Cardiac Surgery Director, Heart and Lung
Transplantation**

University of Maryland Medical Center (UMMC)



Image courtesy Dr. Griffith

Implanted CardioWest TAH-t






Image courtesy SynCardia

Ventricular Assist Devices (VADs)






Image courtesy
SynCardia

Representative Resected Heart




Image
courtesy
Dr.
Copeland




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy SynCardia




Image courtesy Dr. Arusoglu



Image courtesy Dr. Arusoglu